L Number	Hits	Search Text	DB	Time stamp
6	143	@ad<=20010309 and (257/107).ccls. and 'thyristor'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 13:31
7	12	@ad<=20010309 and (257/111).ccls. and 'thyristor'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 13:31
8	20	@ad<=20010309 and (257/112).ccls. and 'thyristor'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 13:32
9	24	@ad<=20010309 and (257/123).ccls. and 'thyristor'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 13:32
10	165	@ad<=20010309 and (257/139).ccls. and 'thyristor'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 13:33
11	110	@ad<=20010309 and (257/157).ccls. and 'thyristor'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 13:33
12	295	@ad<=20010309 and (257/173-175).ccls. and 'thyristor'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 13:34
17	25	@ad<=20010309 and 'thyristor' with 'protection' adj1 'component'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 14:26
18	1	@ad<=20010309 and 'thyristor' with 'protected' adj1 'component'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 14:15
20	45	@ad<=20010309 and 'thyristor' same 'component' same 'voltage' same 'protected'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 14:40
21	52	@ad<=20010309 and 'thyristor' and 'component' and 'over voltage' and 'protected' and 'detector'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 14:40
-	227	@ad<=20010309 and (257/107).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 08:26
-	30	@ad<=20010309 and (257/111).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 13:23
-	348	@ad<=20010309 and (257/173).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 13:23

C:\APPS\EAST\Workspaces\Thyristor\10657899 thyristor overvoltage 257.wsp

-	132	@ad<=20010309 and (257/157).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 13:23
-	336	@ad<=20010309 and (257/134-136).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 13:23
-	138	@ad<=20010309 and (257/388).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 13:23
-	25	@ad<=20010309 and (257/125).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 13:24
-	2278	@ad<=20010309 and (257/355-360).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 11:55
-	742	@ad<=20010309 and (257/361-363).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 13:25
-	332	@ad<=20010309 and (257/546).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 13:25
-	533	@ad<=20010309 and (257/328).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 13:26
-	82	@ad<=20010309 and (363/27).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 13:26
-	265	@ad<=20010309 and (363/96).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 13:26
-	408	@ad<=20010309 and (363/135).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 13:27
-	219	@ad<=20010309 and (363/54).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 13:27
-	96	@ad<=20010309 and (363/85).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 13:27
-	184	@ad<=20010309 and (363/129).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 13:59

-	2	"20040046181"	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 13:28
-	438	@ad<=20010309 and 'thyristor' same 'overvoltage' same 'protection'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 14:20
-	320	@ad<=20010309 and 'thyristor' with 'overvoltage' with 'protection'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 14:40
-	23	@ad<=20010309 and 'thyristor' same 'overvoltage' same 'protection' and 'control terminal'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 14:04
-	0	@ad<=20010309 and 'thyristor' and 'overvoltage protection' and 'control terminal' and 'auxiliary terminal'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 11:45
-	0	@ad<=20010309 and 'thyristor' and 'overvoltage protection' and 'control terminal' and 'auxiliary electrode'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 14:44
-	14	@ad<=20010309 and 'thyristor' and 'overvoltage protection' and 'control terminal' and 'electrode'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 14:14
-	12	("4779126"|"4896243"|"5453384"|"5465189"|"5987462"|"6082000")...	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 14:14
-	0	@ad<=20010309 and 'lateral' same 'thyristor' and 'tigger' same 'overvoltage'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 14:21
-	7	@ad<=20010309 and 'lateral' same 'thyristor' and 'trigger' same 'overvoltage'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 14:21
-	1	@ad<=20010309 and 'lateral thyristor' same 'overvoltage'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 09:36
-	2	("4896243").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 14:43
-	32	@ad<=20010309 and 'thyristor' and 'ESD protection' and 'terminal' and 'electrode'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 15:14
-	749	@ad<=20010309 and (257/350).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 14:57

C:\APPS\EAST\Workspaces\Thyristor\10657899 thyristor overvoltage 257.wsp

–	462	@ad<=20010309 and (257/351).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 14:57
–	327	@ad<=20010309 and (257/352).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 14:57
–	250	@ad<=20010309 and (257/353).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 14:57
–	256	@ad<=20010309 and (257/354).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 14:58
–	1143	@ad<=20010309 and (257/355).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 11:53
–	70	@ad<=20010309 and 'CMOS' and 'thyristor' and 'ESD protection'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/05 15:14
–	96	christian.in. and 'thyristor'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 08:28
–	3	@ad<=20010309 and 'lateral thyristor' same 'anode' same 'cathode' same 'trigger' same 'gate'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 09:39
–	0	@ad<=20010309 and 'lateral thyristor' with 'control terminal'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 09:40
–	0	@ad<=20010309 and 'lateral thyristor' with 'tigger terminal'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 09:40
–	0	@ad<=20010309 and 'lateral thyristor' with 'trigger terminal'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 09:40
–	52	@ad<=20010309 and 'thyristor' with 'trigger terminal'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 09:40
–	390	@ad<=20010309 and 'thyristor' with 'control terminal'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 09:48
–	248	@ad<=20010309 and 'thyristor' with 'control terminal' and 'cathode' and 'anode'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 11:48

C:\APPS\EAST\Workspaces\Thyristor\10657899 thyristor overvoltage 257.wsp

-	7	@ad<=20010309 and 'thyristor' with 'control terminal' and 'cathode' and 'anode' and 'CMOS'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 09:42
-	8	@ad<=20010309 and 'thyristor' with 'control terminal' and 'cmos'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 09:57
-	105	@ad<=20010309 and (257/355-360).ccls. and 'thyristor'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 13:30
-	5	@ad<=20010309 and 'control' with 'lateral thyristor' with 'current'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 10:02
-	11	@ad<=20010309 and 'thyristor' same 'parastic'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 11:32
-	0	@ad<=20010309 and 'thyristor' and 'over' adj1 'voltage' with 'detector' and 'CMOS'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 10:07
-	27	@ad<=20010309 and 'thyristor' and 'over' adj1 'voltage' with 'detector'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 10:11
-	5	@ad<=20010309 and 'thyristor' and ker.in.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 10:15
-	2	("5754380").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 10:15
-	82	@ad<=20010309 and 'thyristor' and christian.in.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 14:14
-	27	'0200547'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 11:42
-	3	'10111462'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 11:43
-	104	@ad<=20010309 and 'thyristor' and 'overvoltage protection' and 'terminal' and 'electrode'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 11:46
-	20	@ad<=20010309 and 'thyristor' with 'control terminal' and 'cathode' and 'anode' and 'over' adj1 'voltage'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 11:48

C:\APPS\EAST\Workspaces\Thyristor\10657899 thyristor overvoltage 257.wsp

-	39	@ad<=20010309 and 'thyristor' with 'control terminal' and 'cathode' and 'anode' and 'overvoltage'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 11:48
-	106	@ad<=20010309 and (257/355).ccls. and 'overvoltage'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 11:53
-	105	@ad<=20010309 and (257/355-360).ccls. and 'thyristor'	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/11/08 11:55